



The above location is a Power Plant in southern California. It has yet to be determined what additional damage has occurred since this fault happened only a few days ago on March 23rd 2002.

Telco pedestal approximately 800 feet away from Sub Station shows destroyed copper Telco pairs and splice connections.

Sub Station
shown in
background





Remains of protector block on the floor above along with burnt and miscellaneous component pieces.

The fiber optic link will now be installed at this location.